


TVA System Status Update

2018 Summary

January 1 – December 31, 2018

CYTD Observed Rainfall vs. Normal



Observed Normal


Location	Observed (in)	Normal (in)	Normal (%)
Above Chatt	66.75	47.04	141.92%
Below Chatt	67.28	54.49	123.48%
System	67.01	50.64	132.32%


CYTD Observed Runoff vs. Normal




Observed Normal

Location	Observed (in)	Normal (in)	Normal (%)
Above Chatt	30.78	22.22	138.54%
Below Chatt	27.66	21.79	126.91%
System	29.27	22.01	133.01%







Fontana 2018




Chatuge 2018



Hiwassee 2018



Nottely 2018




TVA System Status Update

2019 Summary

January 1 – Present


CYTD Observed Rainfall vs. Normal



Observed Normal

Location	Observed (in)	Normal (in)	Normal (%)
Above Chatt	20.21	12.43	162.54%
Below Chatt	22.58	15.74	143.48%
System	21.35	14.03	152.15%


CYTD Observed Runoff vs. Normal




Observed Normal


Location	Observed (in)	Normal (in)	Normal (%)
Above Chatt	17.49	9.42	185.62%
Below Chatt	18.66	10.30	181.11%
System	18.05	9.85	183.30%

System Inflows Above Chattanooga as of April 01, 2019







Fontana 2019



Chatuge 2019



Hiwassee 2019



Nottely 2019

