


Duke Energy Update
September 14, 2021


Lynne Dunn
Duke Energy Hydro Operations

Lake James




100 ft. local datum represents full pond. Lake James below Normal Target to support maintenance activities downstream.

Lake Norman




100 ft. local datum represents full pond. Lake Norman below Normal Target to support maintenance activities downstream.

Lake Tillery




Lake Tillery does not have a target or maximum level. Chart shows 100 ft. as Full Pond

Blewett Falls Lake




Blewett Falls Lake was drawn down in April 2021 and spillway modifications are in progress with expected completion by the end of 2022.⁵

Nantahala Lake



100 ft. local datum represents full pond.

Lake Glenville



100 ft. local datum represents full pond.

Operations Summary

- Since our last meeting, all basins have experienced dryer conditions.
- Blewett Falls Hydro station was fully restored, and all units returned to service on April 2, 2021.

Low Inflow Protocol Status

- Catawba-Wateree
 - Operating under Normal Conditions since February 2018
- Nantahala Area and Yadkin-Pee Dee
 - Operating under Normal Conditions



